

## Annexure C

### PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No 345

Dated: 25/04/2024

It is certified that an inspection team headed by A.E, RWS&S

( Name of Officers with designation ) from Balliguda RWS&S

Inspected the St. John's School

( Name & Address of the school ) on 25.04.24 ( date of inspection ) and on the basis of

Water Test Report ( Attached ) bearing no 07/2024-25 dated 26.04.24

of Balliguda ( RWS&S Lab) certified that the St. John's School

( Name of school ) has safe drinking water facilities for the students and members of staff of staff of the institution School is also maintains the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/ State/ U.T. Govt.

This certificate is valid till one year

Signature with Seal

Name

Designation

Name & Address of the Office/Department

Am  
25/04/2024  
A.E. R.W.S & S.  
Balliguda.

To The Principal

St. John's School, Balliguda  
( Name & Address of the Institution)

Assistant Engineer  
RWS & S Sec Balliguda

Note: The certificate is to be issued by authorized officer /RWS&S Lab / local bodies